



# Projects Track Record

Year	Project/Customer	Location	Scope of Work
2022-2027	COP	Changfang & Xidao	Balance of plant inspection, maintenance and repair for foundations, subsea cables and onshore substation
2022	Century Bladt	Changfang	Paint inspections
2022	JDN	Taipower Phase 1	Paint repair with rope access team
2022	Ørsted	Greater Changhua 1 & 2a	Temporary power solution: generator and service technicians
2021	Boskalis	Yunneng	Bathymetry survey
2021	Hitachi	TPC Phase 1	Temporary power solution: generator and service technicians
2020-2021	FOWI	Formosa 1	Inspection, maintenance and repair, including paint repair, for topside balance of plant
2018-2021	wpd	Yunneng	Bathymetry survey
2020	Shimizu	TPC Phase 1	Temporary power solution: generator and service technicians
2020	JDN	TPC Phase 1	Pre-lay grapnel run
2019-2020	DEME	Anping	Quarterly MBES survey
2019	wpd	GuanYin	Depth of burial survey
2019	JDN	Formosa 1	Pre-lay grapnel run